

CONDITION OF CLASS.TONNAGE OPENING FITTED.

NAME OF VESSEL...."DOÑA AURORA"..... /

Extract from freeboard verification of marking form received

from the .....TRIESTE.....Surveyors dated the....30.9.39.-

Moulded depth	29 ft.	0	ins. /
Corresponding draught	25 ft.	10 $\frac{1}{4}$	ins. /
Moulded depth as shewn on draught sheet	29 ft.	0	ins. /
Tropical Freeboard	2 ft.	10	ins. /
Summer	" 3 ft.	4 $\frac{1}{2}$	ins. /
Winter	" 3 ft.	11	ins. /
W.N.A.	" - ft.	7	ins. /
Fresh Water allowance		6 $\frac{3}{4}$	ins. /

Marked from ~~xxxxx~~ steel upper deck. /

Checked by.....*mm*.....

Date....23.11.39.....



© 2020

Lloyd's Register  
Foundation

W1168-0249