

In damage cases where the Surveyor has not made a special damage report he is required to state whether he

12, 41. F.P. ABOVE  
150 F.

1m, 12, 41.

ent to Chief Surveyors.....

Received from Chief Surveyors.....

ESSEL'S NAME EMPIRE GELT REPORT Grk No. 21760

**For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey CONDITION When due.....

Subject to slightly indented shell plating and framing in way of boiler space (s.s) being dealt with at the Owners' convenience (and to a bower anchor being supplied).

*Wals*  
*4.3.42*  
*[Signature]*



© 2020

Lloyd's Register  
Foundation

W1169 -0061

Were the Tanks been examined internally?	Air and Sounding Pipes <i>See</i>	Stringers, Clamps & Shelves	Standing and Running
Were the Tanks been tested?	Doubling Plates under Sounding Pipes	Salting	