

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Stl T.S.M.V. "SPRING BANK" Report Yls No. 45710**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1<sup>st</sup> Entry. When due \_\_\_\_\_ Revised Rules. \_\_\_\_\_

✱ 100 A.I. (Steel) "With freeboard" Carrying Vegetable oil in Deep Tank  
 1 D<sup>K</sup> (Stl) + Shelter D<sup>K</sup> (Stl - ws)  
 Cell DB 357' 1121t, Tanks between tunnels 115' 251t, D.T.f 32' 1067t, F.P.T. 106t, A.P.T 132t.  
 F.K, 7B.H. (Collision B.H to Shelter D<sup>K</sup>, 6 B.H. to 2<sup>nd</sup> D<sup>K</sup>), pt cem, Lloyds A + CP.



© 2021

Lloyd's Register  
 Foundation

W170-0011