

Anglo Maersk

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Std S M/V ANGLO - SWEDE Rpt. Inc No. 85442
85442(A)

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long

Transverse No. _____

15447

Depth "d" _____

Framing: Table No. _____

Description _____

Longitudinal framing

2nd Longitudinal No. _____

42854

Proportions _____

Length _____

13.70

Depth = _____

Deck Sheerstrake _____

as approved

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100A.1. (Steel) Carrying Petroleum in Bulk.

2 D^{ks} (Stl) & Web Frames. Longitudinal framing

Cell D.B. & E 70' 183t, D.T. & 38' 387t, F.P.T. 240t, A.P.T. 179t

F.K, 17 B.H (11 B.H to upper D^k, 6 B.H. to 2nd D^k) ft Cam, Lloyd's ACP.

P 108', B 29', F 40'. Machinery aft.



© 2020

Lloyd's Register
Foundation

W1171-0011