

F.E.

by Chief Ship Surveyor _____ Received from Chief Ship Surveyor _____

L'S NAME *STR To Se* ^u *M/S ATHELQUEEN* Rpt. *Mdb* No. *13193*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *9758*

Depth "d" *-*

Framing: Table No. *✓*

Description *Longitudinal framing.*

Longitudinal No. *45862*

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{13.3}{1}$

Deck Sheerstrake *1:12, approved 1:04.*

Old Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

100-A-1 (Steel) "Carrying Molasses or Petroleum in Bulk"
2 SKS (Sd) + Web frames, Longitudinal Framing
Cell SB, a E. 63' 297t, D.T.f. 54' 724t, Z.P.T. 1862, A.P.T. 304t.
F.K, 16B.H (10B.H to upper SK, 6B.H to 2nd SK), ph beam, Lloyds A + CP.
P 116, B 34', F 48. "Machy aft"



SJK 28
© 2020

Lloyd's Register
Foundation

To
L.O.



© 2020

Lloyd's Register
Foundation

EE