

Form No. 1A.—1m, 7, 14. T.







GENERAL REMARKS—(continued).

**PARTICULARS FOR RECORD in the REGISTER BOOK.**—Length of Poop 32.91 ft., R.Q.D. ☒ ft., Bridge 98.0 ft., Forecastle 20.0 ft. (in feet and tenths). When the Poop is joined to the B.D., this should be distinctly stated

No. and Material of Decks (if Iron or Steel) and whether wholly or partially covered with wood, and No. of tiers of Beams (this information is to be given in the Register Book) 1 D<sup>th</sup> (Steel)  
 Official No. 142681; Signal Letters \_\_\_\_\_ State if Machinery is fitted aft NO.  
 How are the surfaces preserved from oxidation? Inside Paint and part cement, cement in bilge, engine Outside. paint.  
and boiler room, and peak tanks cement fillets on plate edges in hold tanks.

**PARTICULARS OF WATER BALLAST.**—State whether the Double bottom is constructed on the cellular system or with girders on floors.

Where Fitted.	*Length. Feet.	Water Capacity. Tons.	Where Fitted.	*Length. Feet.
Double bottom, aft,	<u>95.95</u>	<u>226</u>	Fore peak tank,	<u>20.0</u>
Double bottom, under Engines and Boilers,	<u>38.49</u>	<u>133</u>	After peak tank,	<u>20.0</u>
Double bottom, if under Engines only,			Deep tank, aft,	
Double bottom, if under Boilers only,			Deep tank, forward,	
Double bottom, forward,	<u>142.91</u>	<u>390</u>	Other tanks, if fitted,	
	Total capacity of double bottom	<u>749</u>	(If necessary, furnish further information by sketch.)	

\* The wells are not to be included in the lengths of the tanks.

State whether the above have been tested as required by the Rules. YES.

Order for Special Survey No. 5292  
 Date 13.6.17  
 No. 266 in builder's yard.  
 Days of Survey held while building  
1917 Dec 13. 14. 28 Jan 11. 15. 22. 29 Feb 4. 11. 21 Mar 5. 13. 19. 26 Apr 4. 8. 11. 26 May 3. 10. 17. 24 Jun 5. 6. 10. 13. 14. 26 Jul 1. 9. 12. 24. 26 Aug 9. 13. 16. 22. 26. 29. 30 Sep 2. 3. 4. 5. 9. 10. 18. 21 Oct 1. 18. 21. 22. 23. 24. 25. 28. 29. 30

Surveyor's Signature

