

M.V. SHROPSHIRE.Low Done for + LMC - CS.

Port Unit - Examined nos 2, 4, 5 + 6 by cylinders, Covers
 Only pistons valves, connecting rods, with their
 crosshead pins + brasses, to 2 + 4 crank
 shaft pins and brasses, are found in good
 condition, except to 6 crosshead brasses which
 are now renewed.

to 8 Crosshead brasses have now been
 reinstalled as recommended in London Report
 to 104708.

Sterboard Unit - Examined the main Compressor in its
 Only integrity, the intercoolers cleaned and tested.

Auxiliary Unit - Examined the Alfa Diesel Generator to 3
 throughout.

Air Reservoirs + Bottles - Examined Port Upper 350 lb/17
 Air reservoir in its integrity, + the Port
 after blast bottle.

H.O.F.

H.S.

This vessel has now been taken over by Admiralty,