

AMERICAN BUREAU OF SHIPPING

Date **March 17, 1944**

REPORT NO. 3084		REPORT ON CASTINGS OR FORGINGS					PORT OF San Francisco		
VESSEL		INTENDED FOR SHIPBUILDER					SHIPYARD HULL NO.		
STAMPED A. B. 15		ENGINE BUILDER Enterprise Engine Co.					WORKS ENGINE NO.		
No.		PURCHASER					PURCHASER'S ORDER NO.		
ACCEPTED (DATE) 3-21-44		MANUFACTURER Moore Dry Dock Co.					MANUFACTURER'S NO. 6141		
SHIPPED (DATE) 3-17-44		INVOICE NO.		PROCESS OF MANUFACTURE Electric furnace steel		ANNEALED Yes		WEIGHT 10,200#	
DESCRIPTION		PIECE NUMBER	HEAT NUMBER	Test Piece Area	Yield Point per Sq. Inch	Tensile Strength per Sq. Inch	% Elong. in 2"	% Reduction in Area	BEND
1-8 Throw Crank Shaft Dr. 77011		2042	5B625-2	200 200	56000 54500	87000 86000	27.0 28.0	50.0 49.0	180° Good
		BILL RENDERED							
Particulars of Drop Testing, Slings and Hammering.		REMARKS: Rough forging surface examined after annealing and accepted.							
1st Visit Lost Visit No. of Visits Fees Expenses TOTAL		I have to report that the above <u>forging</u> has <u>been</u> examined and tested by me in accordance with the requirements and found to be, so far as could be seen, in good order. Burr SURVEYOR CHIEF SURVEYOR							

This Report is granted subject to the condition that it is understood and agreed that neither the Bureau nor any of its Committees is under any circumstances whatsoever liable for any loss or damage in any report or certificate issued by this Bureau or its Surveyors or in any entry in the Record or other publication of the Bureau or for any error of judgment, default or negligence of its Officers, Surveyors or Agents.