

1m,9,37.

F.E.
(FBD.)

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "VENEZUELA". Rpt. Got. No. 12206.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 15048

Depth "d" 14.92

2nd Long. No. 38352

Proportions = $\frac{L}{D}$ 11.15

Bulb angle

Framing as approved.

Sheerstrake as approved (plus increase)

Without tonnage opening.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **100 A1 'With freeboard'**.

The Summer Freeboard as shown on the attached extract from the Freeboard Verification Form, now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying extract, to be inserted in the certificate of classification.

3 Dks. ~~and shelter deck~~, 'Strengthened for navigation in ice'

Cell DB. 307' 1486t, Tanks in way of tunnels 309t, FPT 76t, APT 52t

FK, 7BH to weather deck, Lloyd's A & CP.

F 85'

O.L. 440.1'

E.S.D.

Lloyd's Register
Foundation

W1178-0103

200



© 2021

Lloyd's Register
Foundation