

1

Sent to Chief Surveyors 15.7.18

Received from Chief Surveyors

VESSEL'S NAME

Sheela Sufland

Report

PhlNo. 2885**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

When due

❖ 100A-1. (Steel) Larning petroleum in bulk

2 str (Steel) & Webframe. Longitudinal Larning

Cell 5B under 5B. 62' 2226 F.P.T. 1596 A.P.T. 306

FK. 14BH (8 to upper str 6 to 2" str. Cen. Axep.

P 97' B 34' F 32' Incl. abt.

M  
16.7.18



© 2020

Lloyd's Register  
Foundation

W1188-0057