

No. in Reg. Book. Survey New York Date, First Survey 5th April Last Survey 6th April 1943
Name of Vessel 3

No. 25874 in R.B. Wreck Book, p. 97 Steel M.V. "Høegh" Date of writing this report 19 MONTH. 3

Vessel's Name M.S. 'Høegh' Silvers (RMC) of Oslo Tons Gross 7715 Net 4730

Built at Copenhagen When 1940 3 Casualty notice sent to Owner Owner's reply

Owner's Name A/S Arizona (Leif Høegh & Co. A/S, Norge.) Address Rådhusplassen, Oslo, Norway

Case previously before Date Particulars of Classification. 4.43 + LMC 3.40
Classing Committee. Last Minute The fish chamber + Lloyd's RMC 4.43
9 No 4 hold port forward chamber 15°F, etc.
carrying cargo oil F.P. above 150°F
in fore & after peak tanks and D.T.
OIL ENGINES

Date of Casualty About 13th July, 1943.
Précis of particulars of Casualty Sunk owing to war causes in the Indian Ocean about the 13th July, 1943.

SOURCE OF INFORMATION.

med) as }
erified } - confirmed in

ed, found or how

al equipment

connected up in

RETAIN

Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—

Asphalt	Good	Engine Room Skylights	Copper, or Y.M. (State if on Fell.)
Steering gear and its connections	"	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Windlass	"	Oil Bunkers	Boats Good
Have pumps been examined and found efficient?	"	Scuppers	Masts, Yards, &c. " from deck
Have Sluice Valves been examined and found efficient?	"	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
Have Watertight Doors been examined and found efficient?	"	Hatches	Equipment letter
Have Ventilators and their Coamings been examined and found efficient?	yes	Planking	Anchors, No. of
Have been examined internally?	"	Caulking	Cables (State if now ranged) no
Have been tested?	"	Treenails	" length mean diam. (on board)
	"	Breasthooks & Stemson	" Rule length size
	"	Transoms, Pointers & Crutches	Chain Locker
	"	Timbers of Frame at openings	Hawsers & Warps sufficient
	"	" " at other places	Standing and Running Rigging good
Air and Sounding Pipes	"	Stringers, Clamps & Shelves	Sails
Doubling Plates under Sounding Pipes	"	Salting (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel is in safe condition and eligible in my opinion to be continued as classed with fresh record of survey 4.43.

Sugge.

Survey Fee (per Section 29)

\$ 30.00

Fees applied for,

16th April 1943

Lloyd's Register Foundation