

12.

Copy

FREEBOARD VERIFICATION FORM FOR STEAMERS.

(When received in London Office)

Vessel's Name

Linerton

Official No.

No. in Reg. Book

Port of Registry (For Foreign Vessels)

Is Steel

State whether Classed by Lloyd's Register

Yes

Name of Owners

Date of Verification

10th Oct. 1919

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned to the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	8	ft.	11½	ins.	
From centre of disc to top of statutory deck line } at awning or part-awning deck . . . }		ft.		ins.	
Fresh water line above centre of disc . . .			7¾	ins.	
Indian Summer line above centre of disc . . .			6½	ins.	
Winter line below centre of disc			6½	ins.	
Winter North Atlantic line below centre of disc				ins.	
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood ^{steel} of iron deck with the vessel's side	}	<i>shaller</i> at main, spar or upper dk.		1¾	ins.
		at awning or pt.-awning dk.			ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

S^d J. S. Leathard Surveyor.

(To be filled up in London Office.)

Statement No. *28223* Date of Committee's Minute*8.10.19*

Particulars for Record in Register Book.	}	Moulded Depth	37	ft.	0	ins.
		Freeboard	8	ft.	11½	ins.
		Corresponding Draught	28	ft.	6	ins.

Freeboards compared and found correct by _____ date _____

Fee paid? _____ Form for Certificate

Instructions _____ date _____

Certificate written _____ Noted for posting _____

Condition of class.



© 2020

Lloyd's Register Foundation

W1196-0118