

Duplicate.

For the information of Surveyors and the Committee only.

Received at

Office

19

Lloyd's Register of Shipping.

(Report on Vessel No. _____)

Port _____

No. 793

SHIP FORGINGS ~~OR CASTINGS.~~

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by Messrs. Skoda Works, Ltd. of Pilsen C. S. R. for the Vessel No. 75, being built by Messrs. Chantiers de Normandie of St. Duvidy have been inspected by me as set forth below and found to be, so far as can be seen, sound and free from defects.
1 complete built Steel Rudder

on Forgings or Castings.

Lloyd's

No. 214

28-5-26

Prague 4th December 1926

C. V. Hughes.

STERN FRAME.

RUDDER FRAME.

STEM.

S. M. C. H. Steel
Forged Annealed

Yes

\$ 255 ^{mm} Built

Finished Condition

28th May 1926

Rudder Stem

Shaft

Rudder stems

I

II

III

IV

44.5

48.2

50.1

47.3

52.5

50.7

31.6

34.2

31.6

34.2

31.6

29.0

180°

180°

180°

180°

180°

180°

✓

✓

✓

✓

✓

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

4 Rudder Pintles } 49.1 & long. 31.6
6 Coupling Bolts }

(if any chargeable) £

to be paid at

Prague.

Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

lap welded or riveted longitudinal joint

BS: T.R.

W1196-0185

© 2020

Lloyd's Register
Foundation