

1m, 12.20.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel Sc Sk "MALACHITE" Report GrK No. 18174

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

First Entry.

When due

100 A. I. (Steel)

1 SK (Stl), "well SK"

Cell D.B. 103' 180t, F.P.T. 13t A.P.T. 2t

F.K. 3 B.H., Cem., Lloyd's A.C.P.

R.Q.D. 107', B 12', F 21', "machinery aft."

Date of Build 1920.

2, 24 P. Gl.

S.S. P. Gl 103-2. 24

8/3/24.



© 2021

Lloyd's Register
Foundation

W12-0039

Angles on upper edge

Spacing

* If Iron or Steel Deck, state if whole or part, and if Wood