

5c, 12, 16.

F.E.

Received by Chief Ship Surveyor 7. 6 18 Received from Chief Ship Surveyor

VESSEL'S NAME Sheers "Kipunezan Maru" Rpt. Kobe No. 2187

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 34/5/92.)

Transverse No. 71. Depth "d" 16.25

Framing: Table No. 3. page Description Bulk angle as approved

Longitudinal No. 21655

Proportions Length = 8.78 Depth =

Bridge Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

100A-1 (Steel) as recommended.

2 Dks (Steel)

Cell DB 263 to 56. F.P.T. 596. a.P.T. 56

FK. 5BH. Cum. area. P 25. B94' F 33'

M 7.6.18



© 2021

Lloyd's Register Foundation

W1208-0230

Poop Deck Stringer Plate, breadth & thickness

Angle on ditto

BEAMS Third and Fourth Deck, Single Angle,

3 x 3