

Rio Jejo

30 JUN 1930

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Sc. "JAUNTY". Rpt. Mta. No. 1256

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey

The class of this vessel was withdrawn from the Register Book in 1923 at the Owners' request.

The S.S. No. 3 for re-classification has been partly held.

The Malta Surveyor, who was authorised to complete the survey, now reports the S.S. No. 3 has been completed and minor repairs effected.

It is submitted the vessel appears worthy to have her class reinstated with record of survey 5.30 and notation of S.S. No. 3-5.30.

+A1

For towing purposes.

5.30 Ply.

S.S. Ply. No. 3-5.30.

1 Dk. (Stl)

Built 1919 - 3 Mo.

Lloyd's A. & C.P.

5 BH Cem.

Cell DB in cross bunker 14' 15t f 18' 10t FPT 15t APT 35t.



27.6.30.


© 2021

Lloyd's Register
Foundation

W1209-0109