



Lloyd's Register of Shipping.

LLOYD'S REGISTER.

LONDON

1 AUG 1922

Willemskade 11^B,

Rotterdam, 28th July 1922.

Letters to be addressed to—
THE SHIPVEYORS.

Dear Sir,

With reference to your letter of the 22nd inst. respecting the scantlings and arrangements of the S.S. "West Caruth", I beg to state that the scantlings of the topsides and side shell plating have been verified from the particulars contained in the plans forwarded by you, and it has been found that the sheerstrake and strake below and also the side shell plating, in the wells and in way of the bridge are in accordance with the plans, without any additional strengthening being provided.

The plating of the bridge and upper decks is in accordance with the plan of midship section, but a rough sketch has been prepared of the upper deck in wells, and the particulars of plating etc. have been indicated thereon.

I might mention that the damage to the bottom is very extensive and that most of the bottom shell plating will require to be renewed.

It is thought well to draw attention to the fact that the repairs, now being carried out, are being done under survey, as arranged by the Owners's Representative here.

The plans forwarded by you are now returned herewith, but I shall be glad if you will return same at your earliest convenience.

I am, Dear Sir,

Yours faithfully,

The Secretary,

London.

W. D. Jones



© 2021

Lloyd's Register
Foundation

W1269-0236

Referred to the Chief Ship Surveyor.

Enquiry to Captain

111 2345678910

111 2345678910

© 2022 Lloyd's Register Foundation

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910

111 2345678910