

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *Steel Deck FOSSA*

Rpt. *Abn*

No. *15780*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/6/02.)

1 1/2" Long
Transverse No. *860*

Depth "d" *9.77*

Framing: Table No. *✓*

Description *angle frames as approved.*

Longitudinal No. *2580*

Proportions $\frac{\text{Length}}{\text{Depth}} =$ *7.44*

Deck Sheerstrake *.50, approved .28*

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*+ 100 A-1. (Steel) For Lifting Services
1 D^{1/2} (Cell)
BK 7/2, 4 BH, Cen, Lloyds A+C.P.*

[Signature]

*W.S.H.
8.10.29.*



© 2020

Lloyd's Register

Foundation
W204-0235