

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book Survey held at Date, First Survey Last Survey

81773 on the Wood, Iron or Steel Le. Iron

TONNAGE Built at Aberdeen By whom A. Hall & Co. Ltd. When 1929-9

GROSS 105 Owners Gaslee & Son Owners' Address

UNDER DEK 104 Managers Port belonging to London

NET 1

When floated or in Dry Dock? Name of Dock Destined Voyage

all DBor DBa feet; uE&B feet; f feet

Capacity tons. FPT tons; APT tons; MT feet tons.

All alterations in the existing records should be underlined.

Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, of the inner bottom plating, especially in the boiler space.

Report, No. 15780 Port Abu

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. & for Special Survey. Date of last Survey and of Periodical Surveys.

Years Assigned and expired. Machinery and Boiler Surveys (including date of N.B., if any).

+100 A1 9.29 +44C 9.29

In King's services

0.8

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR



