

5c, 12.25.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

SH S P. ABOITIZ

Rpt.

JKg

No. 6300

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

1496

Depth "d"

10.04

Framing: Table No.

✓

Description

angle frame as approved

2nd Longitudinal No.

5114

Proportions

Length

12

Depth =

Deck Sheerstrake

as

approved

Revised Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. I. (Steel)

1 D^x (Stl)

F.P.T 195, A.P.T. 185

F.K, 4 B.H, Cem, Clayds A.R.C.

B 21' F 27'.

It is concluded the thickness of the flanged floor and the size of the upper D^x beams is as approved. but the Surveyor should be requested to state if this is so

Spacing