

S.S. "ORMUZ".

It is submitted the Owners be informed that this vessel has been under survey at Amsterdam, Grimsby and London, and the London Surveyors reported in July last that the survey for classification had been completed with the exception that draining arrangements from the spaces above the fore peak tank required to be fitted.

The case received the consideration of the Committee on the 22nd ultimo when the vessel was classed 100A1 "Shade deck", subject to draining arrangements from the spaces above the fore peak tank being fitted.

*Thin arch. now
20 cut 2
should be
32 cut 2*

HL 9.9.22 *Am.S.*



© 2019

Lloyd's Register
Foundation

W1218-0128

Date of Build 1914
7.22 Lon.)
No 3521 subject etc.

21-8-32