

No. 0399

Survey held at Amsterdam Date, First Survey 3rd April Last Survey 18th May 1921
 on the Wood, Iron or Steel T. I. C. 1 "B. I. C. 1" (No. of Visits 1)

NAME: - *14167*
Built at *Bremen* *Vege sack* By whom *Bremer Vulkan* When *1914*.
Owners *Orient Line Navigation Co Ltd* Port belonging to *London*.
Owners' Address *London*.
(if not already recorded in Appendix to Part I)

ed Afloat or in Dry Dock? Afloat Name of Dock ✓ Destined Voyage London

ellDBorDBa feet; uE&B feet; f

capacity tons. FPT tons; APT tons; MT feet; }
Particulars of Classification (which must be inserted
all allegations in the existing records should be underlined)

Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, of the inner bottom plating, especially in the boiler space.

Report. No. Port

CHARACTER.		Year assigned to expire.	Machinery and Boiler Surveys (including date of N.B., if any).
<input checked="" type="checkbox"/> for Special Survey. Date of last Survey and of Periodical Surveys.			
1000			

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; as being detailed in the body of the report, should be summarised in the form shown below. Whenever the state of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case.

cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why
are declined? _____ Was a damage report made _____

OR EXAMINATION AS PER RULE, FOR Classification.

The following requirements have been carried out at this port for the classification of this vessel:
See also first entry by Dept No 0300.

N^o 1-2-3 and 4 holds and tween-decks cleared, close ceiling lifted, N^o 4 and girders ex^a; E & B. space examined, tunnels do. Bunkers partly do; frames, reverse frames, stringers, floors, girders, ends of beams, water-tight keels, rivets and inner surface of the plating, exposed to view, oxidation noted. Tank-tops in N^o 1-2 and 3 holds, coated with asphalt, found good. Some rivets removed and found good; countersinking good. N^o 6-7 and 8 holds and N^o 6 and 7 tween-decks ex^a and good.

CONDITION OF THE		Plates.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Plating	good							
State if Tanks have been examined inside	partly							
State if Tanks now tested								
Bulkheads	good							
Ceiling	"							
Cement or Asphalt	(State which.)							
Rudder								
Steering gear and its connections								
Windlass								
Have Pumps now been examined and found efficient?								
Have Sluice Valves now been examined and found efficient?								
Have Watertight Doors now been examined and found efficient?								
Dblg. Plates under Sounding Pipes								
Engine Room Skylights								
Coal Bunkers, Open'gs, Lids, &c.								
Scuppers								
Cargo Hatchways								
Hatches								
Planking of Wood Vessels								
Caulking								
Treenails								
Breasthooks & Stemson								
Transoms, Pointers, & Crutches								
Timbers of Frame at openings								
Ditto ditto at other places								
Stringers, Clamps & Shelves								
Salting								
(State if examined.)								
Copper, or Y.M. of Wood Vessels								
(State if on Fell.)								
When put on, Month								
Year								
Boats								
Masts, Yards, &c.								
Condition, how ascertained								
(State if wedges removed)								
Sails								
Equipment letter								
Equipment No. of								
Equipment No. of								
Cables (State if now ranged)								
length								
(on board)								
Rule length								
Hawser & Warps								
Standing & Running Rigging								

Observations, Opinion as to Class, Recommendation, &c.:—
 to clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon
 ey, thus, for example:—".....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of
 15," or "to remain as classed and to have record of survey, 1, 15, and the notations of ss No. 1-15 and ptND15, &c."

The above for the information of the Committee.

Section 28)			
Repair Fee (if any)	£	Fees applied for,	19
(if chargeable)	on	Received by me,	19
Fee (if any)	£		

*Fee charged
Trust
on 2nd letter
Feb. 21-1-26*

Chadwick
Surveyor to Lloyd's Register of Shipping.

s Minute TUE JUL 15 1921
 Assigned no action
 TUE. 13 DEC. 1921
 TUE. 22 AUG. 1922
 FRI. 13 APR. 1923
 FRI AUG. 31 1923
 Lloyd's Reg
 Foundation
 W218-0171

Is Certificate required? If so, to be sent to.

ex^{ca} after bunkers are empty.