

S.S. "ZEPPELIN"


S.S. "ZEPPELIN"

As it would appear the plans of the hull of the vessel are not available, and the Owners desire to class ^{the} vessel, it is submitted the Amsterdam Surveyors should be instructed to examine this vessel and obtain all scantlings and particulars and fill in a First Entry Report.

Section 48 of the Rules should be complied with.

The Surveyor should inform the Owners' Representative of the survey he is holding on the vessel.

14/4/21



© 2019

14.4.21.

Lloyd's Register
Foundation

W1218 - 0174

e Boiler

ear fitted