

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel S.S. "HINO MARU"*Rpt. *K032* No. *6621*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long
 Transverse No. *7862*
Depth "d" *-*Framing: Table No. *-*Description *Bulk angles as approved*
2nd
 Longitudinal No. *22329*

Proportions

Length *-*Depth = *-*~~Deck~~ Sheerstrake*as approved.**Revised Rules.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*+ 100 A-1. (Steel)**1 D^K (Pl) + 2nd D^K (Pl) in fore and holds.**FK. Intermediate Bulkhead in fore hold dispensed with 4 B.H. 1st Cen, 2 Logds A+C.P.**Cell DB. 260' 660t, FPT 62t APT 37t**P 32' B 62' F 43'**WJH**25.9.29.*

© 2020

Lloyd's Register
Foundation