

W/221-0016

2 - MAR

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel Sc. "PACIFIC MONARCH", Report Lon' No. 98433A

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/82.)

2nd No. 2 SURVEY PARTLY HELD.

When due 12,31 When proposed to be completed _____

Portion of Survey held, &c., *Held on machinery**Laid up since before*

The 2nd S.S. No.2, due 12,31, has been partly held and to complete same: vessel to be placed in dry dock, bottom and rudder to be examined, cables to be ranged, chain locker to be examined, fore and after peak tanks to be examined and tested, double bottom tank to be examined and tested, coal bunker to be cleared for examination, hand pumps to be tried and freeboard to be verified.

The vessel has been laid up, and the Owners have been asked to furnish the usual undertaking.

The Vancouver Surveyors now forward the attached letter from the Owners.

The year of grace expired 12,32.

The case is submitted for the consideration of the Committee.



© 2020

Lloyd's Register
Foundation