

STERN-POST, do. do.  
RUDDER—A x D\* Table 22

Flat Keel Plate Angles  
Horizontal Plates above floors

Sm. 5.14

1

Sent to Chief Surveyors

17.7.17

Received from Chief Surveyors

VESSEL'S NAME

Steel Barge Navegadora 75 Report L. Jk No. 13915

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

A - (Steel) Barge, carrying petroleum in bulk. For River Service at Tampico.

1 DK (Steel) + 500 frames. Longitudinal framing.

FK. 3 BH. pl. asp.



© 2020

Lloyd's Register  
Foundation

Average space  
BEAMS, Bridge Deck, Angle, Bulb Angle,  
Plate, Tee Bulb or Channel

Tie Plates  
Deck, Material and thickness  
Bridge Deck Stringer Plate, breadth & thickness