

Do. o
Do. o
E
Gro
Less
Less

1

Gascoyne

Sent to Chief Surveyors 21.5.07

Received from Chief Surveyors

VESSEL'S NAME St. Luni S.S. "Leulpue"

Report Es.

No. 25291

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

First entry

When due


+ 100 A 1 ("Steel")

2 DRs (St. V. Leak S) 15 deep framing & 15 web frames.

N. B = Cell DB = 81' u E + B 59' f 153' 634E FPT 65E APT 31E

FK & BK 2" 7BH Cam. Length A + CP P41 F55'

C. K. J.
21/5/07



© 2020

W1242-0008

Lloyd's Register
Foundation