

Cambrian Duchess

F.E.

Received by Chief Ship Surveyor

5/7/13

Received from Chief Ship Surveyor

VESSEL'S NAME

Hb S Nongorod

Rpt.

Hb

No.

25735

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

80.75

Depth "d"

18.91

Framing: Table No.

3 page 15

Description

Bulk angle

Longitudinal No.

31472

Proportions

Length

10.3

Depth

Bridge Deck Sheerstrake as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100A-1. (Stub) as recommended.

\pm 100A-1. (Stub)

2nd (Stub - 2nd Dr W.S.)

MR. CUL DBA 13H n 6x1340 f 170 11236 FRT 1154 APT 604
FK 6BH. Lloyd a x 6P. PHO 3111 FH2