

1.

Sent to Chief Surveyors 9.1.07

Received from Chief Surveyors

VESSEL'S NAME *St. Triple S. S. "Margelmu"* Report *Dev.* No. *58760*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*First entry**When due*

+ A1 ("Steel") "With foulboard."

"In Service between Grimsby & Rotterdam, Hamburg & Antwerp."

2 DR (U Ste - ws)

N.B = DB & E 16' 11" FPT 33" APT 40"

FK 7BH Asp Lloyd's AYCP P33' B117' F36'



C. H. 2020

9/1/07

Lloyd's Register
Foundation

W1243-0229