

Russhin Maru No 3

F.E.

Received by Chief Ship Surveyor *14. 9. 04*

Received from Chief Ship Surveyor _____

VESSEL'S NAME *Sta. S. S. "Catalina"*

Report *Nov.* No. *47593*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>2/20"</i>	<i>Proportions</i>
Spar Sheerstrake . .	<i>"</i>	<i>"</i>
Description of Framing:— <i>Deep (Bulb angle) framing, as approved</i> (viz., ordinary, deep, zed, channel or bulb-angle). <i>on the plan of midship section.</i>		

Ceiling has been omitted from the bulk top of this vessel, at the request of owners, per letter attached to the first entry report of sister vessel "Caroni".

In other respects This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+ 100 A 1 ("Steel")* as recommended.

+ 100 A 1 ("Steel")

2 DRs (Stl) & deep framing.

M. B = Cell DB = 86' x E7B 68' f 118' 546 E FPT 60 E APT 20 E

FX 5BH Am. Lloyd's A & CP P 21' B 87' F 33'



C. A. J.

14/9/04
Lloyd's Register
Foundation

W1243-0255