

Awning or Shelter Deck,
or Pt. Awning Deck.

STEEL STEAMER.

Preliminary Report.

No. 14914.

State if Report is also sent on the Machinery of the Vessel.

of *Swansea*.

Date of completion of Report 19. 9. 19.

Received at London Office

Date, First Survey 15. 9. 19.

Last Survey 18. September 1919.

Rig

by held at

S.S. "MOGADOR" ex "GIBRALTAR"

Master *A. F. Rigot.*

Year of Appointment (1) As Master in service of owner of present vessel - 1919
(2) As Master of this vessel - 1919

Built at *Kiel*

When built 1905. Launched

By whom built *Howaldtswerke*

Owners *Compagnie Maritime*

Managers *Castanier & Co. du Protectorat du Maroc.*
(Where necessary to be entered in Reg. Book.)

Residence

Port belonging to *Boulogne*

If Surveyed while Building, Afloat, or in Dry Dock *At Saltch.*

LENGTH on keel as per Rule	Ft.	Ins.	BREADTH Moulded	Ft.	Ins.	DEPTH, ACTUAL Do.	Ft.	Ins.	No. of Decks with flat laid No. of Tiers of Beams

FRAMING.

FORGINGS AND CASTINGS.

KEELSONS AND STRINGERS.

Awning or Shelter Deck Stringer Plates.

Upper or Second Deck Stringer Plate.

Third Deck Stringer Plates, br'dth & thck'ns

Fourth and Fifth Deck Stringer Plate.

Poop Deck Stringer Plate, breadth & thickness

Bridge Deck Stringer Plate, br'dth & thickness

Forecastle Deck Stringer Plate, br'dth & th'kns

BULKHEADS.

W. T. BULKHEADS

COLLISION

LONGITUDINAL

STIFFENERS.

Are the outside Plates doubled two spaces of Frames in length?

Are the Sluice Valves and Watertight Doors in efficient working order?

W1246-0128

Lloyd's Register Foundation

With, or without Freeboard, as condition of Class

Committee's Minute

Character assigned

WED. AUG. 4 1920

TUE. AUG. 17 1920

© 2020 Lloyd's Register