

22 tunnel
Hpl. 14972

Submitted the Hartlepool Surveys be requested
state the size of the tunnel wall suction
this has been omitted from their report

J.F.S.
10.8.14



© 2020

Lloyd's Register
Foundation
W147-0293

Working Pressure 180 tta Tested by hydraulic pressure to 360 tta Date of test 29/5/14 No.