

Im.821.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stal S.S. "BARKABOOK"*

Rpt. *Bel*

No. *8723*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *105*

Depth "d" *19.83*

Framing: Table No. *3*

Description *Channels with reversed frame*

Longitudinal No. *54600*

Proportions

Length *10.6*
Depth

Shade Deck Sheerstrake *as approved*


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ❖ 100-A-1. (Stal) *Shade Deck*

3 Dhs (Stal U-NS) + Shade Dh (Stal tracks)

Cell Dhs 442' 2173t, Tanks between tunnels 127' 322t, FPT 160t, APT 164t, FK 2. BK 2", 9BH, Cuv, Hlyhs Ar CP, F 58' on Shade Dh.

M

8.4.22



© 2020

Lloyd's Register
Foundation