

1,500,1037.

1

*Commo
es*

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Sheess Ardgoorn

Report

SK

No. *17312*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

*The Committee have approved as a War Emergency Measure of the Kedge
Anchor & Downton pump being dispensed with at Owner's request for
the duration of the War.*

100A-1. (Steel)

2 DXs (Steel)

Cell DB. 334' 1029 L. A.P.T. 206

FK. 6 BH. Cam Lugs over. P34 B III F 47

Carrying oil fuel F.P. above 150° F in double bottom

The Certificate of Classification, to be endorsed
"Cargo battens not fitted," ^{in three decks} and the same
notation to be printed in the Register Book.

M
12. 6. 18



© 2021

Lloyd's Register
Foundation

W1262-0067