

F.E.

Received by Chief Ship Surveyor 8. 10. 03

Received from Chief Ship Surveyor

VESSEL'S NAME SS. S. S. "Zambesia" Report Sub. No. 3699

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report. 24/5/92.)

CLASSIFICATION.

| Items. | Additions (if any) required by Rules, or as approved. | On account of:— |
|---|---|-----------------|
| Main Sheerstrake . . | <u>1/20" but Awaiting deep sides increased</u> | |
| Spar Sheerstrake . . | | |
| Description of Framing:— <u>Ordinary</u> . (viz., ordinary, deep, zed, channel or bulb-angle). | | |


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A 1 ("Steel") "Awaiting deep" with freeboard," as recommended. The Summer freeboard of 9' 2 1/2" from centre of disc to top of statutory deck line at Awaiting deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

∇ 100 A 1 ("Steel") "Awaiting deep with freeboard":

1 DR & Awaiting DR (pt Ste - Teak S)

N. B = Cull DB a 61' in E & B 31' f 92' 263 E APT 146

FR 4BH Cull Lloyd's A & CP



© 2020

Lloyd's Register Foundation
8/10/03
W1266-0286