

27 NOV 1933

s.s. "TORLAK"

The 2nd S.S.No.2 became due in 7,32 and no part of this survey has been held.

The vessel is laid up at Aalesund and the usual undertaking has been furnished.

On 23rd instant the Bergen Surveyor was authorised to furnish a report giving particulars of the estimated weight of the materials of the vessel, which it was stated had been sold for breaking up.

A letter ^{by cable} has now been received from the Surveyor stating that the vessel has been sold for breaking up, and that a certificate is desired to enable her to proceed from Aalesund in ballast to Leith, and the Owners desire to know if a general examination afloat of the hull, machinery and boilers will be accepted.

It is submitted the Surveyor be informed that provided a general examination in accordance with the provisions of Circular No.1605 be held with satisfactory results, a certificate to enable the vessel to proceed to Leith to be broken up might be issued.

27.11.33

Messrs. Jobson & Co. Ltd. are
London Agents for Metal
tries to Ltd



© 2020

Lloyd's Register
Foundation

W1268-0035