

REC'D NEW YORK Nov. 27. 1916 (Received at London Office WED. 20 DEC. 1916 No. 14a)
REPORT of SURVEY for REPAIRS, &c.

of writing Report Nov. 14 1916 When handed in at Local Office Nov. 14th 1916 Port of PORT ARTHUR, ONTARIO.
Survey held at PORT ARTHUR, ONTARIO. Date, First Survey Nov. 8th Last Survey Nov. 13th 1916
on the Wood, Iron or Steel SCREW STEAMER "BLAAMYRA" Master C. L. STEPHENS

TONNAGE:- Built at PORT ARTHUR, ONTARIO By whom WESTERN DRY DOCK & SHIP-BUILDING CO., LTD. When 1916 11
ROSS 2436.73 Owners GREAT LAKES TRANSPORTATION COMPANY, Port belonging to KRISTIANIA
UNDER DECK 2251.09 Owners' Address MIDLAND, ONTARIO.
ET 1484.05 (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? In Dry Dock Name of Dock W.D.D. & S.B.CO. LTD. Destined Voyage LAUNCHING.
B=Cell DBor DBa 76 feet; uE&B 38 feet; f 96 feet;
al capacity 328 tons. FPT 79.68 tons; APT 105 tons; MT feet tons.
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.-All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.
1st ENTRY REPORT HEREWITH 1st ENTRY REPORT HEREWITH.
Society's Freeboard (if assigned) as painted on Ship and now verified 4 ft 1 1/2 in.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined?
Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR DAMAGE SUSTAINED WHILE LAUNCHING OCTOBER 25th, 1916.
KEEL PLATES #8 and 9 and D STRAIN NO. 7 STARBOARD SIDE indented, taken off, rolled fair and returned.
D #6 and D #9 slightly indented, faired in place.

Summary of Damage Repairs table with columns: Plates, Frames, R. Frames, Floors, Beams, Str. Plates, Dk. Plates, Other Items. Includes sections for Present Condition of the Vessel and General Observations.

General Observations, Opinion as to Class, Recommendation, &c.:
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of ss No. 1-11 and ptND11, &c."

THIS VESSEL IS IN EFFICIENT CONDITION AND ELIGIBLE IN MY OPINION TO REMAIN AS CLASSED FOR CLASS 11/16, PORT ARTHUR, ONTARIO.

Survey Fee (per Section 28) \$75.00
Special Damage or Repair Fee (if any)
Travelling Expenses (if chargeable)
Second Surveyor's Fee (if any)
Committee's Minute
Character Assigned
Fees applied for, Nov. 27. 1916
Received by me, Nov. 27. 1916
Surveyor to Lloyd's Register of British & Foreign Shipping
FRI. 28 DEC. 1917
TUE. 8 JAN. 1918
TUE. 28 MAY. 1918
TUE. AUG. 13. 1918
TUE. SEP. 24. 1918
TUE. 12 NOV. 1918
Lloyd's Register Foundations
W1268-0077