

3m. 100

1

Stylanos Chandris' Catapring

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel SS "E.A. MORSE" Report Balt. No. 2766

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 34/5/92.)

Nature of Survey

When due

Steel. Four Anchors & 210 fathoms of Chain Cable tested by the American Bureau Surveyors, & the American Committee have assigned the figure 1.

✱ 100 A.1. (steel) "Shelter Dk. with freeboard"

1 Dk. (steel) of Shelter Dk. (steel) & Webframes. "Longitudinal framing."

Cell DB 349' 1360t. MT 30' 587t. FPT 73t. APT 46t.

FR. 6 BH to Shelter Dk. 1 BH to upper Dk. Conn. P 34' F58' on Shelter Dk.

W127-0025

Particulars for Record

Moulded Depth

Freeboard

8 ft. 7 ins.

Inches in Ship.

7e)  
te)

Lo

50

5x

52

60

32x

g.

31