

5c,7,16.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME STEEL S.S. "KARACHI MARU" Rpt. Kobe No. 2590

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 79Depth "d" 16-0'Framing: Table No. 3Description Channel as approvedLongitudinal No. 30415Proportions $\frac{\text{Length}}{\text{Depth}} =$ 10.7Awning
Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A.1. (steel) "Awning Dk with freeboard," as recommended. The Summer freeboard of 9'-3½" from centre of disc to top of statutory deck line at Awning deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

2 Dks (steel) and Awning Dk (steel)

Cell DB 334' 1118 t. FRT 126 t. APT 93 t.

FK. Collision BH to Awning Dk. 5 BH to Upper Dk. Cent. Lhys. A.C.P.

W1272-0054

© 2021
Lloyd's Register
Foundation