

1.

"Oneka"

Sent to Chief Surveyors 23. 6. 03

Received from Chief Surveyors

VESSEL'S NAME See. S. S. "Schuylkill" Report Sub No. 13655

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First entry When due

± 100 A 1 ("Steel") Shelter Deck with freeboard,

2 DR (Stl) & deep framing & shelter DR (Stl)


N.B = Cell DB a 146' u E 23' f 171' 12105 DT a 42' 10896 FPT 82L APT 45L

FK 7BH Am Plogh A + CP

C. H. J.
23/6/03

It should be pointed out to the Surveyors that the notation of "Plogh A + CP" has been omitted from the Committee's minute.

C. H. J.



© 2020

Lloyd's Register
Foundation

W1276-0087