

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stl Saddle S J. J. 11 Rpt. Sng lth No. 1654
17628

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.



("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

^{1st Long}
Transverse No. 1200Depth "d" 9Framing: Table No. ✓Description angle frames as approved^{2nd} Longitudinal No. 5040Proportions $\frac{\text{Length}}{\text{Depth}} =$ 12~~Deck~~ Sheerstrakeas approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ A. I. (Steel). Jerky Service between Singapore Island and Permas
1 D" (Steel)

F.K, 4 B.H, Cem, Plyds A CP.


© 2020

Lloyd's Register
Foundation

W1287-0267