

5c, 12.25.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Sta T.S. TIA JUANA Rpt. Bel No. 9945

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long

Transverse No.

4575

Depth "d"

13.25

Framing: Table No.

Description

Bulk angle frames as approved

2nd Longitudinal No.

19825

Proportions

Length

20.33 1/2 U.D.

Depth =

13.45 1/2 Trunk

Deck Sheerstrake


as approved

Revised Rules


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A.1. (Steel). Carrying Petroleum in Bulk
1 D^W (Steel)

Wing tanks of 286t, wing tanks a 356t, F.P.T. 60t, A.P.T. 75t
F.K, 7 B.H, pt Cem, Lloyds A CP.
P67', TRUNK 20H', F 34'. machy apr.



12.4.28



© 2019

Lloyd's Register
Foundation