

Copy

FREEBOARD VERIFICATION FORM FOR STEAMERS.

When received in London Office

Port _____

Vessel's Name

Tredinnick

Official No. _____

No. in Reg. Book _____

Port of Registry (For Foreign Vessels) _____

~~Iron or Steel~~

State whether Classed by Lloyd's Register

Yes

Name of Owners _____

Date of Verification

2 Feb 1921

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line *3* ft. *7½* ins.From centre of disc to top of statutory deck line }
at awning or part-awning deck . . . } ft. ins.Fresh Water line above centre of disc . . . *6½* ins.Indian Summer line above centre of disc . . . *6* ins.Winter line below centre of disc . . . *6* ins.~~Winter North Atlantic line below centre of disc~~ . . . ins.Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of ~~wood~~ *steel* iron deck with the vessel's side } at ~~main, spar or~~ upper dk. *1¾* ins.

} at awning or pt.-awning dk. ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

55 J Macdonald Surveyor.

(To be filled up in London Office.)

Statement No. _____

Date of Committee's Minute

*10.12.20*Particulars for record
in Register Book.Moulded Depth . . . *28* ft. *6* ins.Freeboard . . . *3* ft. *7½* ins.Corresponding Draught *25* ft. *3* ins.

Freeboards compared and found correct by _____ Date _____

Is fee paid? _____

Form for Certificate

Instructions _____

Date _____

Certificate written _____

Noted for posting

Condition of class


© 2019

Lloyd's Register
Foundation