

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME *Steel S.S. "BOGSTAD"*Report *Ark.*No. *17683.*For the CHIEF SHIP SURVEYOR ~~MASTERS ENGINEER~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.6.02.)

Nature of Survey.....

When due.....

Efficient repairs have been effected to damage sustained by striking quay wall.

* 100 A.1. (steel)

2 Dks (steel).

Cell DB 331' 994 t.

APT 20t.

FK.

7BH.

Cem.

Lloyd's A7C.P. P 39', B 230', F 45'.

M. A. S.
12-8-20
 © 2020
 Lloyd's Register
 Foundation