

Do.  
E  
Gro  
Less  
Less  
E

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel Barge "No 151"*

Rpt. *96 Puerto*

No. *40211*  
LA. *2342*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *40.125* Depth "d" *10.95*

Framing: Table No. *3* Description *Single Angle*

Longitudinal No. *52.6*

Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{10.74}{}$

~~Deck~~ Sheerstrake *and other scantlings as approved for the A Class*

*This vessel was dismantled after erection and shipped to Manatitlan, Mexico, where she has been re-erected.*

*The Rudder has not been fitted.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*A - (Steel) Barge for being towed for river purposes only*

*1 Dk. (Steel)*

*FK, 3 BH, Cen,*

*AD*  
*7.7.21*