

3m. 2.24.

1

Gwentgate

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel Ss "FOREST GATE"

Report

Gls

No. 43988

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

1st Entry.

When due

+ 100 A.I. (Steel)

1 Sk (Rtl)

Cell D.B. 204 H54t, F.P.T. 72t, A.P.T. 35t.

F.K. 4B.H. Cam, Lloyd A + C.P.

P 17', B 58', F 23'.

The Certificate of Classification, to be endorsed
"Cargo buttons not fitted," and the same
notation to be printed in the Register Book.



© 2021

Lloyd's Register
Foundation

W1308-0091

20.9.22