

F.E.

ved by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME *Stl & M/V KONSAN MARU* Rpt. *Kb* No. *6658*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

*1st Long*Transverse No. *6987*Depth "d" *18' 5"*Framing: Table No. *✓*Description *Bull angle frame as approved*Longitudinal No. *22100*Proportions $\frac{\text{Length}}{\text{Depth}} =$ *15.12*

Deck Sheerstrake

*as approved**Revised Rules*

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.I. (Steel).

1 D¹⁰ (Stl)

Cell D.B. 230' 7695, tanks in way of tunnel 1735, F.P.T. 515, A.P.T. 355

F.K. 5 B.H. pt Cen, Lloyds A.C.P.

P 27', B 63', F 28'.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2021

Lloyd's Register Foundation

W1310-0206

Spacing

34 FRAME

24