

# REPORT ON ELECTRIC FITTINGS.

(OTHER THAN FOR THE PROPULSION OF THE VESSEL)

WFO. 14 MAR. 1923

Date of writing Report

19

When handed in at Local Office

13. 3.

1923

Port of

Middlesbrough

No. in Survey held at  
Reg. Book.

Date, First Survey

10. 1. 23

Last Survey

22. 2.

1923

(Number of Visits.....)

on the "I. S. Kenmore"

Tons { Gross  
Net

Built at Haverton Hill / Tees By whom built Furness S/B Co. Ltd

Yard No. 29

When built 1923

Owners Johnston Line

Port belonging to

Liverpool

Electric Light Installation fitted by Furness Shipbuilding Co. Ltd

Contract No.

When fitted 1923

## System of Distribution

Double Wire

Pressure of supply for Lighting

100

volts, Heating

volts, Power

100

volts.

Direct or Alternating Current, Lighting

Direct

Power

Direct

If alternating current system, state frequency of periods per second

Has the Automatic Governor been tested and found efficient when the whole load is suddenly thrown on or off

yes ✓

Generators, do they comply with the requirements regarding overload

yes ✓

, are they compound wound

yes ✓

are they over compounded 5 per cent.

level

, if not compound wound state distance between each generator

Where more than one generator is fitted are they arranged to run in parallel

No ✓

, is an adjustable regulating resistance fitted in

series with each shunt field

yes ✓

Are all terminals accessible and clearly marked

yes ✓

, are they so spaced or shielded that they cannot be accidentally earthed,

or short circuited

yes ✓

Are the lubricating arrangements of the generators as per Rule

yes ✓

## Position of Generators

Engine Room Floor Level Starboard Side

is the ventilation in way of the generators satisfactory

yes ✓

, are they clear of all inflammable material

yes ✓

if situated near unprotected woodwork or other combustible material, state distance of same horizontally from or vertically above the generators

and

, are the generators protected from mechanical injury and damage from water, steam or oil

yes ✓

are their axis of rotation fore and aft

yes ✓

Earthing, are the bedplates and frames of the generating plant efficiently earthed

yes ✓

are the prime movers and

their respective generators in metallic contact

yes ✓

Main Switch Boards, where placed

Engine Room Aft B'head Starboard Side

If the generators and main switchboard are not placed in the same compartment, is each generator provided with

a fuse on each insulated pole as near as possible to the terminals of the generator, additional to that provided on the main switchboard

Switchboards, are they placed in accessible positions, free from inflammable gases and acid fumes

yes ✓

are they protected from mechanical injury and damage from water, steam or oil

yes ✓

, if situated near unprotected

woodwork or other combustible material, state distance of same horizontally from or vertically above the switchboards

and

are they constructed wholly of durable, incombustible non-absorbent materials

yes ✓

, is all insulation of high dielectric strength and of

permanently high insulation resistance

yes ✓

, if semi-insulating material is used, are all conducting parts connected to one pole

insulated from the slab with mica or micanile and the slab similarly insulated from its framework

yes ✓

, and is the

frame effectively earthed

yes ✓

Are the following fittings as per Rule, viz. :— spacing or shielding of live parts

yes ✓

, accessibility of all parts

yes ✓

, absence of fuses on back of board

yes ✓

, proportion of omnibus

bars

yes ✓

, individual fuses to voltmeter, pilot or earth lamp

yes ✓

, connections of switches

yes ✓

Main Switchgear, description of switchgear for each generator and each outgoing circuit, and arrangement of equalizer switches

D.P. Switch + Fuse for each Generator + Outgoing circuit. D.P. Change-Over Switch for connecting Generator alternatively to Bus-Bars (Fuses, Porcelain A.O. Pattern)

Instruments on main switchboard

2

ammeters

1

voltmeters

synchronising device for paralleling purposes.

Earth Testing, state what means are provided at the main switchboard for indicating the state of the insulation of the system Two 16 c.p. lamps in series + middle point earthed connected to each bus-bar by means of switch fuse

Switches, Circuit Breakers and Fusible Cut-outs, do these comply with the requirements of the Rules

yes ✓

Section and Distribution Boards, is the construction, protection, insulation, material, and position of these as per rule

yes ✓



If portable lamps for use in dangerous spaces are supplied, are they of a type approved by the Home Office.....

[illegible]



All Conductors are of annealed copper conforming to British Standard Specification No. 7.  
The Insulated Conductors are guaranteed to withstand the immersion and resistance tests specified in the Rules.  
The foregoing is a correct description.

F. S. G. FURNESS SHIPBUILDING CO. LIMITED

P. S. G. F. F. S. G. F. F. S. G. F.

Electrical Engineers.

Date 8th March 1923

#### COMPASSES.

Distance between electric generators or motors and standard compass 150 ft

Distance between electric generators or motors and steering compass 140 ft

The nearest cables to the compasses are as follows:—

A cable carrying 6 Ampères 3 feet from standard compass 4 feet from steering compass.

A cable carrying 3 Ampères inside feet from standard compass - feet from steering compass.

A cable carrying - Ampères - feet from standard compass - feet from steering compass.

Have the compasses been adjusted with and without the electric installation at work at full power. yes

Has the effect of switching on and off circuits, motors and other electro-magnetic apparatus within the vicinity of the compasses been noted. yes

The maximum deviation due to electric currents was found to be nil degrees on all course in the case of the standard

compass, and nil degrees on all course in the case of the steering compass.

For Furness Shipbuilding Co. Ltd.

J. Mc Govern

Builder's Signature.

Date 8/3/23

Is this installation a duplicate of a previous case no If so, state name of vessel ✓

General Remarks (State quality of workmanship, opinions as to class, &c. This installation has been fitted)

in accordance with the Rules: is of good materials and workmanship and on completion was examined under full working conditions and found satisfactory

It is submitted that  
this vessel is eligible for  
THE RECORD.

Elec. Light

15/3/23

Total Capacity of Generators 22½ Kilowatts

The amount of Fee ... £ 18 : 15 : 13.3.19.23

Travelling Expenses (if any) £ See debit book.

Committee's Minute

FRI. 23 MAR. 1923

Assigned

W. Morrison

Surveyor to Lloyd's Register of Shipping.

1m. 3. 22.—Transfer.  
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

OFFICE OF  
MAR. 1923  
These particulars are  
al Letters (if any)  
Official Number.  
7,199.  
Date, and Port of  
Other British or  
Foreign Built.  
tish  
Number of Decks  
Number of Masts  
ged ...  
n ...  
id ...  
eries ...  
d ...  
newwork and descr  
essel ...  
Number of Bulkheads  
Number of water balla  
and their capacity in  
al to quarter the depth from  
to bottom of keel  
Description  
Inverted  
Surface Co  
Triple Exp  
Single end  
Number ...  
Iron or Steel ...  
Loaded Pressure  
Gross  
er Tonnage Deck  
e or spaces between  
et or Trunk ...  
castle... inclu  
ge space Hou  
on Deck ...  
Houses ...  
Houses Rou  
t House ...  
es for machinery, a  
ction 78 (2) of the  
94 ...  
ss of Hatchways  
Gross Tonnage  
ctions, as per Cont  
Registered Ton  
1.—The tonnage of th  
propelling machi  
2.—The undermentio  
ecastle  
n space und  
dge  
n space und  
sage at aft  
Name of Mast  
of Owners  
p, Residence, and  
hnston Line  
Royal Liver  
Liverpo  
ed 16th  
71008) Wt. 23011/10



© 2021

Lloyd's Register  
Foundation