

F.E.

Received by Chief Ship Surveyor 2-1074

Received from Chief Ship Surveyor _____

VESSEL'S NAME

Steelss Mena

Rpt.

SubNo. 27946

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

34.45

Depth "d"

11.0

Framing: Table No.

3 page 9

Description

Single angle

Longitudinal No.

4203

Proportions

Length

Depth =

9.89~~Deck~~

Sheerstrake

56 of an inch instead of 34 as reqd.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A-1. (Steel) Ocean Trawler, as recommended

100A-1. (Steel) Ocean Trawler.1 Dr.BK 8". 4 BH. can Lugs area 276 F 17'

© 2021

Lloyd's Register
Foundation

W1317-0180