

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *St. Sc. "JOHORE MARU"* Rpt. *Kob* No. *7879*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

*1st Longt.*Transverse No. *13325*Depth "d" *19.59*Framing: Table No. *✓*Description *Bulb angle frames as*Longitudinal No. *36285**approved*

Proportions Length *12-61*
Depth =

Deck Sheerstrake *as approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ *100 A1 (Steel)**2 DKS. (Stl)**bell. D.B. 354' 1322 t, Tank over thrust recess 37t, FPT 127t, APT 127t.**FK. 7 BH. cern, Lloyds A & CP.**P. 32' B 140' F 43'**29.9.32**J.M.*

© 2021

Lloyd's Register
Foundation*W1318-0151*